

## LEICA DNA03 DIGITAL LEVEL SETTINGS

The following settings can be set from the “**Meas & Rec**” screen which comes up when the level is first turned on. If the level is in “**PROGRAM**” mode, exit the program to see the “**Meas & Rec**” screen.

---

### SET UNITS

From the “**Meas & Rec**” screen: Press the < **SHIFT** > < **PROG** > keys.

From the “**MENU**” screen, select < **2 ALL SETTINGS** > then press the < **enter** > key.

From the “**ALL SETTINGS**” screen, select < **4 UNITS** > then press the < **enter** > key.

From the “**SET UNITS**” screen, set the following:

Distance : **metre**  
Temp. : **° C**

Highlight < **SET** >, then press the < **enter** > key.

---

### SET DATE AND TIME

From the “**Meas & Rec**” screen: Press the < **SHIFT** > < **PROG** > keys.

From the “**MENU**” screen, select < **2 ALL SETTINGS** > then press the < **enter** > key.

From the “**ALL SETTINGS**” screen, select < **5 DATE / TIME** > then press the < **enter** > key.

From the “**SET DATE / TIME**” screen, set the following:

Date : **dd.mm.yyyy**  
Time (24HR) : **hh:mm:ss**

Highlight < **SET** >, then press the < **enter** > key.

---

### SET CURVATURE CORRECTION OFF

From the “**Meas & Rec**” screen: Press the < **SHIFT** > < **PROG** > keys.

From the “**MENU**” screen, select < **2 ALL SETTINGS** > then press the < **enter** > key.

From the “**ALL SETTINGS**” screen, select < **2 MEASURING** > then press the < **enter** > key.

From the “**MEASURING SETTINGS**” screen, set the following:

CodeSet : **Before**  
Decimals : **0.00001m**  
GSI-Format : **GSI – 8**  
EarthCurv : **No**

Highlight < **SET** >, then press the < **enter** > key.

---

## SET INCREMENT MODE

From the “**Meas & Rec**” screen: Press the < **SHIFT** > < **USER** > keys.

From the “**FUNCTIONS**” screen, select < **4 PtID & INCREMENT** > then press the < **enter** > key.

From the “**PtID & INCREMENT**” screen, set the following:

Running PtID	
PTID:	<b>1</b>
INCR:	<b>1</b>

Highlight < **SET** >, then press the < **enter** > key.

---

## SET MEASUREMENT MODE

From the “**Meas & Rec**” screen: Press the < **MODE** > key.

From the “**MEASURE MODE**” screen, set the following to:

Mode	:	<b>Mean s</b>
n	:	leave blank
n min	:	<b>3</b>
n max	:	<b>10</b>
sDevM / 20m	:	<b>0.00002 m</b>

Highlight < **SET** >, then press the < **enter** > key.

---

## ASSIGN “CODE” TO USER KEY

From the “**Meas & Rec**” screen: Press the < **SHIFT** > < **PROG** > keys.

From the “**MENU**” screen, select < **1 QUICK SETTINGS** > then press the < **enter** > key.

From the “**QUICK SETTINGS**” screen, toggle “**USER-Key**” to “**Code**” like the following:

Contrast	:	50%
EarthCurv	:	No
USER-Key	:	<b>Code</b>
Decimals	:	0.00001m

Highlight < **SET** >, then press the < **enter** > key.

---